

---

Subject: After Windows update, all com ports are renumbered

Posted by [Kurt](#) on Thu, 12 Jul 2018 17:15:54 GMT

[View Forum Message](#) <> [Reply to Message](#)

---

We've noticed this with Windows update 1803.

We're currently working on the issue, so far it looks like a change with the Windows O/S update installation procedure.

I will update when with new developments.

Kurt

---